

## *Compact Systems: VS-Assistant Vortex 800 does not install Windows 98*

The first part of the installation (copying files at most) is done without a problem.

The second part after reboot does not proceed. Instead the boot screen of Windows 98 Second Edition with the moving waterfall line at the bottom appears. There is no more progress.

Â

This effect is caused by USB function in the BIOS. To change that perform these steps:

- Reset the BIOS to the Default settings
- Find parameter **IDE-Mode** and configure it as **Legacy Mode**.
- Find parameter **IRQ9** and assign this to **PCI/PNP**. This should be the default settings, but check it.
- Find parameter **USB EHCI Handoff** and configure it as **Disabled**.
- Save the new configuration and reboot the system

The installation of Windows 98 should proceed normally.

Â

*Unique solution ID: #1112*  
*Author: Support*

# *Compact Systems: VS-Assistant Vortex 800 does not install Windows 98*

*Last update: 2018-04-17 15:12*